



## INSERTOS

Tipo	Referência para Pedido	Classe	C/Cobertura UP20M	NX2525	Cermet	S/Cobertura UT120T	ISO Passo mm (fios/pol.)	Dimensões (mm)			Geometria
								D1	S1	Re	
Perfil Parcial 60°	<b>MTTR436000</b>	G		●	●	●	-0.8	12.7	4.76	0	<b>MTTR/L(60°)</b>   Corte à direita.
	R436001	G	●	●	●	●	1.0–1.75	12.7	4.76	0.1	
	L436001	G	●			●	1.0–1.75	12.7	4.76	0.1	
	R436002	G	●	●	●	●	2.0–2.5	12.7	4.76	0.2	
	L436002	G		●	▲	●	2.0–2.5	12.7	4.76	0.2	
	R436003	G	□	●	●	●	3.0–3.5	12.7	4.76	0.3	
	L436003	G		●	▲	●	3.0–3.5	12.7	4.76	0.3	
	R436004	G		●	●	●	4.0–4.5	12.7	4.76	0.4	
Perfil Parcial 55°	<b>MTTR435501</b>	G		●	▲	●	(28–10)	12.7	4.76	0.1	<b>MTTR/L(55°)</b>   Corte à direita.
	R435502	G		●	●	●	(16–8)	12.7	4.76	0.2	
	R435503	G		●	▲	●	(11–8)	12.7	4.76	0.3	

ROSQUEAMENTO

### NORMA DE PROFUNDIDADE DE CORTE

- A tabela ao lado mostra as profundidades de corte em usinagens externas de roscas métricas ISO.
- Quando utilizar classes de Cermet para usinar aços inoxidáveis, aumente o número de passes em 2–3 vezes.



### ROSCA MÉTRICA

P (Passo)	0.75	1.00	1.25	1.50	1.75	2.00	2.50	3.00	3.50	4.00	4.50
<b>h<sub>1</sub></b>	0.46	0.61	0.77	0.92	1.07	1.23	1.53	1.84	2.15	2.45	2.76
<b>h<sub>2</sub></b>	0.35	0.47	0.59	0.70	0.82	0.94	1.17	1.41	1.65	1.87	2.11
<b>r (Raio da Ponta)</b>	0.11	0.14	0.18	0.22	0.25	0.29	0.36	0.43	0.50	0.58	0.65
<b>Número de Passes</b>	<b>1</b>	0.18	0.20	0.20	0.25	0.25	0.25	0.30	0.30	0.35	0.35
	<b>2</b>	0.13	0.15	0.18	0.20	0.20	0.25	0.25	0.25	0.30	0.35
	<b>3</b>	0.10	0.10	0.12	0.15	0.20	0.20	0.20	0.25	0.25	0.30
	<b>4</b>	0.05	0.10	0.12	0.15	0.15	0.15	0.20	0.20	0.20	0.25
	<b>5</b>		0.06	0.10	0.10	0.12	0.15	0.15	0.20	0.20	0.25
	<b>6</b>			0.05	0.07	0.10	0.10	0.10	0.15	0.20	0.20
	<b>7</b>				0.05	0.08	0.10	0.15	0.15	0.20	0.20
	<b>8</b>					0.05	0.10	0.10	0.15	0.15	0.15
	<b>9</b>						0.08	0.10	0.10	0.15	0.15
	<b>10</b>						0.05	0.09	0.10	0.10	0.15
	<b>11</b>							0.05	0.10	0.10	0.10
	<b>12</b>								0.05	0.10	0.10
	<b>13</b>									0.05	0.10
	<b>14</b>										0.06

(Nota) O primeiro passe causa uma grande pressão na aresta de corte. Para evitar danos, mantenha a profundidade de corte entre 0.4–0.5mm no máximo.